

► Objectives

► Contacts

► Join

► Links

► News

► Front Page

Oberon Tarana Heritage Railway Inc.

Survey Photographs

These photographs were taken by OTHR members during our survey operations on the track and were used in preparing our Business Plan.

The Copyright of these photographs remains with the source / photographer and these photographs may not be reproduced without their permission.

CLICK IMAGE TO VIEW FULL SIZE



Some of the original "roundback" sleepers (possibly 1923)



A general view of the condition of the line near Hazelgrove



What can be achieved by one person.



The transom top timber girder br. spanning Snakes Valley Creek



The transom top timber girder br. spanning Emu Valley Creek



Probably deliberate removal of the embankment



One of the concrete culverts - all in excellent condition



The worst culvert in an area where many sleepers were stolen.



Trike storage area



Fish River bridge



Southern half of the Fish River Bridge



This is a transom-top plate web girder.



Plate web girder from the top showing the weathered transoms



Plate web girder bracing.